

EXHIBIT B

Site Visit 04.27.2024
CIS



(View of North Façade, Front)

Site Visit 04.27.2024
CIS



(View of North West Front Porch)

Site Visit: 04.27.2024
CIS



(View of North East Front Porch).



(View of North East Front Porch) / (North East Façade)

Site Visit: 04.27.2024



(View of East Facade)



(View of East Facade)



(View of East Façade, at porch and porch foundation):



(View of East Façade, at porch and porch foundation):



Brick Foundation rear facade

Site Visit: 04.27.2024



(west side view)

Site Visit: 04.27.2024



(View of Front Door, on North)

Site Visit: 04.27.2024



(View of Front, Interior at Foyer, at Main Structure)

Site Visit: 04.27.2024




(View of Interior)

Site Visit: 04.27.2024



(View of Interior, Kitchen, Addition 1 & 2)

Site Visit: 04.27.2024



(View of Interior,- tile flooring with mastic containing asbestos)

Site Visit: 04.27.2024



(View of Interior, Room 3 – Bathroom in the room)

Site Visit: 04.27.2024



(View of Interior, attic)